MANUFACTURING DEMAND, FUNDAMENTALS OF MANUFACTURING











Dr. Markos Sándor © BME Department of Manufacturing Science and Technology http://www.manuf.bme.hu - 2 -

Production process







Virtual Production/Manufacturing







Design in integrated CAD/CAM environment







Interfaces





STEP / IGES /STL / VRML / XML











Product development





- Prototype production
- ▶ "0" serial
- The quality of the prototype production defined by the environment!

Forrás: AUDI



Manufacturing life cycle







Assembled unit







Dr. Markos Sándor © BME Department of Manufacturing Science and Technology http://www.manuf.bme.hu - 10 -



- Type of assembling
 - Manual assembling
 - Automatic assembling
 - Assembling by robots
- Analysis of the construction
- Dimension chain analysis, calculation of the closing member
- Assembling root and net
- Setting a minimum number of parts
- Determination of mounting pieces
- Assessment of the automatic assembling capabilities
- Assessment of the robotic assembling capabilities
- Time and cost calculation of the assembling process
- Calculation of efficiency indicators



Drawings, machining demands







Dr. Markos Sándor © BME Department of Manufacturing Science and Technology http://www.manuf.bme.hu - 12 -

Accuracy requirements, cost











Definition: DFM is the method of design for ease of manufacturing of the collection of parts that will form the product after assembly.



'Optimization of the manufacturing process...'

DFA is a tool used to select the most cost effective material and process to be used in the production in the early stages of product design.

Machining:







A1) Understand manufacturing problems/issues of current/past products

to learn from the past and not repeat old mistakes

A2) Design for easy fabrication, processing, and assembly

Designing for easy parts fabrication, material processing, and product assembly is a primary design consideration.

P1) Adhere to specific process design guidelines.

It is very important to use specific design guidelines for parts to be produced by specific processes such as welding....,

P2) Avoid right/left hand parts.

Avoid designing mirror image (right or left hand) parts. Design the product so the same part can function in both right or left hand modes.

P3) Design parts with symmetry.

Design each part to be symmetrical from every "view,..





P4) If part symmetry is not possible, make parts very asymmetrical.

The best part for assembly is one that is symmetrical in all views.

P5) Design for fixturing.

Machine tools, assembly stations, automatic transfers and automatic assembly equipment need to be able to grip or fixture the part *in a known position* for subsequent operations.

P6) Minimize tooling complexity by concurrently designing tooling.

Use *concurrent engineering* of parts *and* tooling to minimize tooling complexity, cost, delivery leadtime and maximize throughput, quality and flexibility.

P8) Specify optimal tolerances for a Robust Design.

Design of Experiments can be used to determine the effect of variations in all tolerances on part or system quality.

P9) Specify quality parts from reliable sources.





- **P10) Minimize Setups.** For machined parts, ensure accuracy by designing parts and fixturing so all key dimensions are all cut in the same setup (chucking). Removing the part to re-position for subsequent cutting lowers accuracy relative to cuts made in the original position. Single setup machining is less expensive too.
- **P11) Minimize Cutting Tools.** For machined parts, minimize cost by designing parts to be machined with the minimum number of cutting tools. For CNC "hog out" material removal, specify radii that match the preferred cutting tools (avoid arbitrary decisions). Keep tool variety within the capability of the tool changer.
- **P12) Understand tolerance step functions and specify tolerances wisely.** The type of process depends on the tolerance. Each process has its practical "limit" to how close a tolerance could be held for a given skill level on the production line. If the tolerance is tighter than the limit, the next most precise (and expensive) process must be used. Designers must understand these "step functions" and know the tolerance limit for each process.



DFM Examples







Machining demands (requirements)





- Milling (plane, pocket, groove, contour, surface, screws, rest...)
- Sparking (sinking, wire, orbital)
- Grinding (plane, cylindrical groove, screws..)
- Polishing
- Surface treatment (sand blasting, "skinning"..)
- Surface coating



Analysis of the machining demands









No	Name	Dimension	Tolerance	Ra	Machining
1	Fixing hole	Ø 65 ±0.02		3.2	Drilling Boring Chamfering
2	Outside diameter	Ø99±0.01		1.6	Rough turning Fine turning
3	Face	60±0.02	p ±0.03	1.6	Rough turning Fine turning
4	Extruder wing			0.025	Rough milling Fine milling Rounding Polishing
5	Keyways 2 times.	10.2 +0.05 0	p ±0.1,	3.2	Shaping



Manufacturing, machining environment



Compliance: B axis
Functionality
Flexibility
Positioning and repetition accuracy
Spindle speed
Rigidity
Damping

Specific machine cost: Classical: 15 EUR/hours 3 ax NC: 20 - 40 EUR/hours 5 Ax NC:40 - 70 EUR/hours Depent on dimension







Integrated manufacturing

- Drill Chamfering Thread milling tools
- Boring bars
-
- □ Milling Drilling
- □ Milling Drilling Turning
- □ Milling Drilling Turning Grinding
- □ Milling Drilling Turning– Grindings Laser "milling"

D

- □ Turning Drilling
- □ Turning Drilling Milling
- □ Turning Drilling Milling Gearing
- □ Turning Broaching Milling

•

- □ Wire EDMing
- Wire EDMing– Water jet machining



Integration of machining processes







Dr. Markos Sándor © BME Department of Manufacturing Science and Technology http://www.manuf.bme.hu - 23 -

Hybrid machining









Types of manufacturing:

Continuous: The machine tool layout (organization) is based on the manufacturing sequence. (mass production) Workshop based: The machine tool needed by one operation are grouped in one workshop. (single production)



Production and Manufacturing



Production: manufacturing + administration

Manufacturing: Process + storing and transportation

Process : metal forming (removing) process

Raw material	Production	Product
Bulk	Pre-production	One type material, one or some
Sheet	Part-production	pieces
Wire	Assembling	Several type of material, hundred
Power		thousand parts

PRE-PRODUCTION	PART PRODUCTION	ASSEMBLING
CASTING	METAL CUTTING	JOINING
WELDING	GRINDING	SETTING, BALANCING
DIEING	SPARKING	SURFACE TREATMENT
STAMPING	COATING	CONSERVATION
CUT-OFF	HEAT TREATMENT	PACKAGING
PREPRODUCT	PART	PRODUCT





ETAP:	That period of production by which product parts reach the same state condition. Different types of operation. (pre-production, part-production, assembling)
GROUP OF OPERATION:	The same type of operations. (turning operations)
OPERATION:	Sum of activities which is realized in the same workpiece clamping on the same machine. An other definition: part of activity which is completed
GROUP OF OPERATION ELEMENTS:	The same type of operation elements. (drilling operation elements)
OPERATION ELEMENT:	Metal forming or removing process realized on the same workpiece surface with the same tool, with the same cutting conditions. Sum of motions
MOTION:	People or machine made activities which has separated functions regarding the operation . (clamping, entry, clear. E.t.g.)
MOTION ELEMENT:	Activity which has not got separate function regarding the operation (start, switch,)



Surface generation methods



According motion geometry (Theory of the surface production):

a. Casting, Forming

- The tool is the negative replica of the workpiece
- Simple tool motion
- Machining time is small
- Expensive, complicated tooling
- Even surface no furrows on it
- Typical mass production

b. Profiling, copying

- Cutting edge is generated according a surface curve
- Tool-motion along <u>a directrix</u>.
- Machining program is delivered by the tool
- Fine surface, furrows are one direction
- Typical mass production



c. Generation

- The machined surface is generated by the tool
- workpiece rolling on the common rolling elements.
- Complicated tool and tool- motion
- Once or two times furrowed surface
- Small and large series production
- Turning, milling, grinding

d. Shaping

- Motion of a universal tool along surface curves (generatrix and directrix)
- Complicated tool motion 2-3-4-5 D axis tool path control
- Two times furrowed surface
- Long cutting time (high speed cutting)
- Typically single production







Classification of the manufacturing processes



Acc	cording metal removing process :		
Ma	in group - Group – Subgroup – Codes		
1.	Casting, Forming	4.	Joining
2.	Forging, Dieing	5.	Coating
3.	Separation	6.	Heat-treatment

∉An example of the subgroup





Process planning activity plan







Levels and steps of the process planning







Dr. Markos Sándor © BME Department of Manufacturing Science and Technology http://www.manuf.bme.hu - 31 -

Place of the pre-planning in the process hierarchy









Operation sequence planning

- Determination of the machining needs
- Define machining modes
- Datum plate (surfaces) selection
- Machine-tool selection
- Clamping fixture selection
- Define operation boundaries
- Define of the operation sequence
- Determination of the intermediate contours
- Operation: part of the manufacturing process realized on one machine and in one clamping.





Source: Miko





- Rule 1: avoid qualifying and requalifying operations where possible
- Rule 2: requalifying operations are necessary after heat treatment
- Rule 3: perform process critical operations as early as possible
- Rule 4: perform product critical operations, identified by close tolerances, as early as possible
- Rule 5: perform product critical operations, identified by surface finish, as late as possible



- Rule 6: operations producing datum or location surfaces must be performed before the operations using those surfaces as datums or for location
- Rule 7: the sequence should minimize the number of setups and machine changes
 - match sequence to manufacturing cell layout
- Rule 8: datum changes should be minimized within a setup
- Rule 9: the sequence should minimize manufacturing tolerance stackups
 - finishing sub-tree should match design dimension graph
 - manufacturing datum sequence should match GD&T datum sequence

- Rule 10: for rotational parts, do not use tapered or shaped surfaces or their end points as datums or for location (exception is between center location)
- Rule 11: if a known sequence exists between two operations (see stock removal sequencing) then the first operation should be closer to the datumhierarchy tree center or else in a separate branch





Sequence of operations









Metal removing plan

Operation planning

- (Generation of operation steps)
- Cutting tool selection
- Integration of operation steps
- Determination of the sequence of the operation steps
- Cutting tool layout preparation

Operation step: part of the manufacturing process where the machining allowance is removed by a given tool.









Planning operation steps



Tool path planning **Determination cutting** parameters Ta (mm) (m/min) n (1/min) f (mm)





Dr. Markos Sándor © BME Department of Manufacturing Science and Technology http://www.manuf.bme.hu - 38 -

Description of the operation steps (elements)





Erect	BME Manufacturing	OPERATI	ON ELEMEN.	т		Nu Fle	mbarofOp. m.: 7	Page mucher:
rug:	ineering Department	rtment				2		
66033	ACLER :	Ball oldabe tet			Ide	Identification of part:		
Matez		Eaw dimonsio 42x47,5x 3	n: Mat. 38 condition:	Name of the op Nagy menetk	nton Olás- észítés	Ide of	ntification. Operation:	Number of Op. Plan
	A †	2 contractions of the second s	50 32 A - A 5x45 ^e hamfers 2 0 <u>M5</u> 2 hotes 66	hanters		₹ A		
No.	Operation element	No. of sunface	Cutting	g to cil.	₩ [m/m in]	ո [1/min]	f [mm/fog, mm/rev]]	a [nīn]
No.	Operation element Face milling bottom surface;	No. of sunface	Cutting	g ito cil.	[mmin] 305	n [1/min] 6472	f [mm/feg, mm/rev]] 0,11	° [mm] 1
No. 1 2	Operation element Face milling bottom surface; Spot drilling 2 marufacturing holes	No. of sufface	Cutting ø2 mm;	g to di.	[mmin] 305 90	[1/min] 6472 5700	f [nom/fog, mm/rev]] 0,11 0,08	[mm] 1 1
No. 1 2 3	Operation dement Face milling bottom surface; Spot drilling 2 mawufacturing holes Spot drilling 2 holes in bottom surface	No. of sunface	Cutting ø2 mm; ø2 mm;	g to cil.	[m [*] /min] 305 90 90	[Jmin] 6472 5700 5700	f [mm/feg. mm/rev]] 0,11 0,08 0,08	[mm] 1 1 1
No. 1 2 3 4	Operation element Face milling bottom surface; Spot drilling 2 manufacturing holes Spot drilling 2 holes in bottom surface Drilling 2 manufacturing holes	No. of sufface	Cutting \$\$2 mm; \$\$2 mm; \$\$3 mm, L = 1	g boû	[mm/min] 305 90 90 90	[1/m in] 6472 5700 5700 8500	f [nm/feg. mm/rev]] 0,11 0,08 0,08 0,08	[mm] 1 1 1 1,5
No. 1 2 3 4 5	Operation element Face milling bottom surface; Spot drilling 2 marufacturing holes in bottom surface Drilling 2 marufacturing holes Drilling 2 holes in bottom surface	No. of surface	Cutting \$\$2 mm; \$\$2 mm; \$\$3 mm, L = 1 \$\$4 mm;	g bol	[m [*] min] 305 90 90 90 90	[_min] 6472 5700 5700 8500 8500	(mm/feg, mm/rev]) 0,11 0,08 0,08 0,08 0,08 0,1	[mm] 1 1 1 1,5 2
No. 1 2 3 4 5	Operation element Face milling bottom surface; Spot drilling 2 maroufacturing holes in bottom surface Drilling 2 holes in bottom surface Drilling 2 holes in bottom surface Countersinking 2 maroufacturing holes	No. of sufface	Cutting \$\$2 mm; \$\$2 mm; \$\$3 mm, L = 1 \$\$4 mm; \$\$4 mm;	g b d 14 mm;	(m [*] in) 305 90 90 90 90 90	pmm] 6472 5700 5700 8500 8500 8500	+ [mm/feg. mm/rev]] 0,11 0,08 0,08 0,08 0,1 0,1	[mm] 1 1 1,5 2 0,5
No. 1 2 3 4 5 6 7	Operation element Face milling bottom surface; Spot drilling 2 marufacturing holes in bottom surface Drilling 2 holes in bottom surface Drilling 2 holes in bottom surface Countersinking 2 marufacturing holes Countersinking 2 through holes	No. of sufface	Cutting \$\$2 mm; \$\$3 mm, L = 1 \$\$4 mm; \$\$4 mm; \$\$6 mm;	g bd	(m [*] in) 305 90 90 90 90 90 90	[1,5,5700] 5700 55700 8500 8500 8500 8500	f [mm/feg. mm/feg] 0,11 0,08 0,08 0,08 0,1 0,1 0,1 0,1	[mm] 1 1 1,5 2 0,5 0,5
No. 1 2 3 4 5 6 7 8	Operation element Face milling bottom surface; Spot drilling 2 marufacturing holes in bottom surface Drilling 2 marufacturing holes Drilling 2 notes in bottom surface Counters inking 2 marufacturing holes Counters inking 2 through holes Tapping two through holes	No. of ruface	Cutting \$\$2 mm; \$\$2 mm; \$\$3 mm, L = 1 \$\$4 mm; \$\$4 mm; \$\$6 mm;	g b d	[m ³ in] 305 90 90 90 90 90 90 90 10	p.m.ii) 6472 5700 5700 8500 8500 8500 8500	* [mm/frey]] 0,11 0,08 0,08 0,08 0,1 0,1 0,1 1	[mm] 1 1 1,5 2 0,5 0,5



Manufacturing/Cutting technology







Dr. Markos Sándor © BME Department of Manufacturing Science and Technology http://www.manuf.bme.hu - 40 -

Description of the machining process



Function – Sub function	Shape Material → Reduce Material → Mechanical
Reference	Alting,Leo. "Manufacturing Processes Reference Guide." 1994
Date	April 2003
Author	Joaquín Aca





Process parameters for turning







Turning



TABLE 22.5 Representative Machining Conditions for Various Work and Tool–Material Combinations

		Rake Angles (degrees)		Cutting Speed	
Work Material	Tool	Back	Side	m/min	fpm
B1112 steel	HSS	16	22	69	225
	WC	0	3	168	550
	Ceramic	- 5	- 5	427	1400
4140 steel	HSS	12	14	40	130
	WC	0	3	91	300
	Ceramic	- 5	- 5	274	900
3620 steel	HSS		uncoated		100
	WC		uncoated		400
	WC	C	bated with '	ГіС	600
	WC	coa	ted with A	L_2O_3	1100
	WC, AL_2C	D_3 with LFC	3		1300
18–8 steel (stainless)	HSS	8	14	27	90
	WC	4	8	84	275
	Ceramic	- 5	- 5	152	500
Gray cast iron (medium)	HSS	5	12	34	110
	WC	0-4	2–4	69	225
	Ceramic	- 5	- 5	244	800
Brass (free-machining)	HSS	0	0	76	250
	WC	0	4	221	725
Aluminum alloys	HSS	35	15	91	300 plus
	WC	10-20	10-20	122	400 plus
Magnesium alloys	HSS	0	10	91	300 plus
	WC	10	10	213	700 plus
Titanium (turning)	WC	0	5	46	150

Lathe turning operation

Single-point tool

Feed: 0.38 mm/rev (0.015 ipr) Depth: 3.18 mm (0.125 in.)



Dr. Markos Sándor

© BME Department of Manufacturing Science and Technology

http://www.manuf.bme.hu



Machinability of different workpiece materials



















Material	Melting temperature Tm	Roughing (30 A)	Finishing (5 A)
		mm3/min	mm3/min
Zink	420	1000	120
Magnesium	Magnesium 600		100
Aluminum	660	500	80
Brass	900	320	50
Copper	1080	220	30
Steel	1350	160	25
Nickel 1450		150	20
Hardmetal	3000	60	10
Tungsten	3400	40	6

MRR=40*I**/**Tm¹.23

Dr. Markos Sándor © BME Department of Manufacturing Science and Technology http://www.manuf.bme.hu

Copper electrode material, max. 7A/ mm2

Components of the machining time







Dr. Markos Sándor © BME Department of Manufacturing Science and Technology http://www.manuf.bme.hu - 47 -

Changing of the setup time depend on the part numbers

Effect of the Setup time to the norm time:



A norm time for a given part is:

 $t_{d} \equiv t_{f,m} (1 + \frac{t_{ki} + t_{psz}}{100})$



Components of the setup time

[ft]

Preparation

- Program loading
- Tools to the tools magazine
- Tool pre-setting
- Fixture positioning, alignment
- Workpiece clamping, positioning fixing
- Zero-point determination
- Program writing, program inspection
- Soft jaw machining

Finishing

- Workpiece unclamping
- Cleaning, deburring
- Measuring and inspection









- The cutting time mainly depend on the cutting speed and the feedrate (cutting parameters).
- Alternative solutions to reduce the cutting time:
- Improved cutting tool quality
- Improved cooling and lubrication
- Contraction of the operation elements,
- Multi-tool tool holders,
- Multi-spindle machining
- All the solutions cause the increasing of the production cost.



Classification of product costs





Direct costs can be traced to a specific product. Indirect costs cannot be traced to a specific product.



Changing of the cost components







$$K_{e} = \frac{K_{esz}}{n} + K_{egy} + K_{ea}; \quad K_{egy} = \sum_{i=1}^{m} C_{Mi} \cdot t_{Ni}$$
$$K_{a} = \frac{K_{asz}}{n} + K_{agy} - K_{f}; \quad K_{agy} = ua$$
$$K_{s} = \frac{K_{ssz}}{n} + K_{sgy}; \quad K_{sgy} = ua$$

$$K_{gy} = K_e + K_a + K_s$$

where:

- K_{gy} product direct manufacturing costs
- $\mathbf{K}_{\mathbf{e}}~$ cost of the pre-production

- $\mathbf{K}_{\mathbf{s}}$ assembling cost
- $\mathbf{K}_{\mathbf{a}}$ cost of the part manufacturing





- \mathbf{K}_{esz} tool and fixture cost of the pre-production
- $\mathbf{K}_{\mathbf{asz}}$ tool and fixture of the part manufacturing
- $\mathbf{K}_{\mathbf{ssz}}$ tool and fixturing cost of the assembly
- **n** number of the produced parts
- \mathbf{K}_{egv} production cost of the pre-product
- **K**_{agy} Cost of the part production
- \mathbf{K}_{sgv} cost of the assembling process
- $\mathbf{K}_{\mathbf{ea}}$ Material cost of the pre-product
- $\mathbf{K_f}$ Cost (price) of the chip, garbage price (it can increase the cost, for instance: dangerous waste)
- C_{M} Cost of the machine tool, or workspace (Ft/min)
 - (machine tool, equipment, assembling workspace etc.)
- $\mathbf{t}_{\mathbf{N}}$ time of the observed operation \mathbf{m} operation number





$$C_{M} = (1 + \frac{R}{100})b + \frac{Ag(\frac{1}{a} + \frac{Rg}{100})}{60H_{\acute{e}v}}$$

- b Labour cost, Ft/min;
- *R* labour cost overhead %;
- Ag Price of the machine tool, Ft;
- a Amortization time, year;
- Rg Cost connected to the usage of the machine tool
 - (maintenance, energy, emulsion, overhead, %.)
- Hév machine tool operation time, hours.





Direct cost (Kd):

- Material
- Operation, machining
 - 1. setup
 - 2. clamping, unclamping
 - 3. machining
 - 4. tool
 - 5. fixture
- Measuring, inspection
- Repearing, refuse replacement
- Transportation

Indirect costs (Kov):

- Kov Ft/piece = Kd*overhead/100
- (Kd = direct part costs)

Typical overhead tasks:

- process planning
- NC programming
- scheduling







Ka /piece = part mess * specific (unit) cost (Ft/kg) = part volume * specific(unit) cost (Ft/cm3)

Ke/piece = setup time*workplace cost/batch number



Kb/piece = (clamping +unclamping time) * workplace (machine tool) cost (CM Ft/min) alternative

Kb/piece = (clamping +unclamping time (into fixture)) * labour cost (CL Ft/min) +

= (clamping +unclamping time (into machine tool)) * Workplace (machine tool) cost (CM)

Km/piece = (Σ cutting time+ Σ time of the rapid motion+ Σ tool changing time)*CM





Ksz/piece = Σ Cutting time*CT (Ft/min)

(CT = depreciation + re-sharpening + insert + pre-setting)

alternative

Ksz/piece = Σ (tooling cost * cutting time/tool life)

alternative

Ksz/piece = Σ tooling cost /batch number

Kk/piece = (fixture cost + Maintenance cost)/yearly (planned) batch number

Kme/piece = Σ measuring, inspection time * sampling rate*batch number * Workplace cost (CI Ft/min)

Kjs/piece = refuse percentage* Km/piece

Ksz/piece = Σ transportation, storing cost/batch number



Cost estimation based on feature recognition



Feature Recognition Applications

	Part Name	Mold Base		Part Name	Housing Blank
The second secon	Size	9" x 12" x 1.75"		Size	2.25" Dia. x 3.375"
1111	Material Grade	Steel SAE 4140		Material Grade	Steel SAE 12L14
	CAD File Type	3D Model .step file		CAD File Type	SolidWorks .sdlprt
	Equipment	Mazak VCN		Equipment	Hardinge T42
1 1 1 1 1	Operations	2 Axes Machining		Operations	2 Axes Machining
	Manufacturing Time	310 Minutes		Manufacturing Time	4.39 Minutes
	Time to Estimate	7 Minutes		Time to Estimate	3 Minutes
	Cost	\$573.12		Cost	\$21.30

	Part Name	Lock Plate		Part Name	Mounting Block
	Size	8" x 5" x 1.25"		Size	4.2" x 1.62" x 1.25"
-	Material Grade	Steel SAE 1018		Material Grade	Alum. SAE 6061-T6
	CAD File Type	SolidWorks		CAD File Type	Parasolid .x_t
	Equipment	HAAS HMC		Equipment	Mori Seiki MV 55
	Operations	2 Axes Machining		Operations	2 Axes Machining
	Manufacturing Time	98 Minutes		Manufacturing Time	41 Minutes
	Time to Estimate	4 Minutes		Time to Estimate	4 Minutes
	Cost	\$167.10		Cost	\$73.42

	Part Name	Top Plate	2D Estimating Incorporates SolidMarksTM 2D Estimating		
	Size	24" x 21.5" x .062"	3D Estimating incorporates Soldworks ^{IIII} – 2D Estimating		
	Material Grade	Steel SAE 1018	Standard CAD and graphic file formats are supported.		
16452201	File Type	AUTOCAD 2D.dxf			
	Equipment	Amada Laser			
THAT SALL	Operations	2 Axes Cutting	AutoCAD Soud Edge D PTC		
	Manufacturing Time	11.53 Minutes	2 2 5117		
	Time to Estimate	5 Minutes			
	Cost	\$31.03	CATA SOMMOTES PROJENGINEER		



Dr. Markos Sándor © BME Department of Manufacturing Science and Technology http://www.manuf.bme.hu

Control questions



- Geometrical modeling solution. Data (geometrical model) exchange between CAD systems, interface possibilities. Rework requirements, and application.
- Surface creation methods. Meaning of the forming, profiling, generation, shaping.
- Connection between tool path planning and the surface generation.
- Definition of the Machinability. Machinability of different workpiece materials. Machinability parameters: metal removal rate, specific cutting force...
- Definition of the machining operation. Operation planning. Operation sequencing rules.
- Levels and steps of the operation planning. Process planning hierarchy.
- Components of the machining time. Machining time and cost estimation.
- Tool path generation process steps in CAM system. CAM strategies, solutions.





Thank you for your attention !

WWW.MANUF.BME.HU

